

May '99 Occurrence List

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
05/01/1999	1	Personnel Injury Occurs following Venting of High Pressure Helium Gas.	CH-BH-BNL-BNL-1999-0012	SC	Off-Normal	Notification	05/11/1999	05/11/1999
Total for Class		1						
05/01/1999	2	Natural Gas Pipe Breach Releases 600 lbs of natural gas when a DOE Contractor Cuts Buried Gas Line with Backhoe.	HQ-GOPE-FETC-1999-0004	FE	Off-Normal	Notification	04/06/1999	05/24/1999
05/01/1999	2	Crude Oil Vapor Flash Fire Occurs when Worker Lights Propane Torch to Secure Tape at Point of Loosened Flange.	HQ-SPR- M-1999-0005	FE	Off-Normal	Final	05/26/1999	07/15/1999
05/01/1999	2	Chemical Exposure/Spill During Chemical Injection Process, Spraying Employee and Surrounding Area..	ALO-KO-SNL-NMFAC-1999-0004	DP	Off-Normal	Final	05/06/1999	07/15/1999
Total for Class		3						
05/01/1999	3	Unreviewed Hazard Associated with Liquid Nitrogen.	CH-AA-ANLW-TREAT-1999-0002	NE	Off-Normal	Update/Final	05/25/1999	06/21/1999
05/01/1999	3	Oxygen Analyzer Found Out of Calibration discovered During Quarterly Instrument Loop Calibration Surveillance.	SR-WSRC-ITP-1999-0014	EM	Off-Normal	Final	05/14/1999	06/30/1999

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
05/01/1999	3	Package Containing Explosive Material Fails and Requires Re-Packaging without incident.	ALO-KO-SNL-10000-1999-0002	DP	Off-Normal	Final	05/20/1999	06/29/1999
05/01/1999	3	Failure to document LCO (Event upgraded from NR to Unusual);	SR-WSRC-TRIT-1999-0008	DP	Unusual	Final	04/21/1999	05/30/1999
05/01/1999	3	Field Laboratory Personnel receive Methylene Chloride Exposure above OSHA Short-Term Exposure Limits.	ORO-BJC-PGDENVRES-1999-0003	EM	Off-Normal	Update/Final	05/27/1999	07/07/1999
05/01/1999	3	Mercury Spilled from a Barometer, Releasing 0.6 pound and Requiring Reporting of Event as Off-Normal.	RFO-FHLL-FACOPS-1999-0002	EM	Off-Normal	Final	05/11/1999	07/07/1999
05/01/1999	3	Failure to meet special conditions of safety evaluation report: sludge depth limit not verified or clarified.	RL-PHMC-SNF-1999-0014	EM	Unusual	Update/Final	05/28/1999	07/12/1999
05/01/1999	3	1400 lbs of Refrigerant Escapes from Chiller;	CH-PA-PPPL-PPPL-1999-0002	SC	Off-Normal	Update	05/27/1999	07/16/1999
05/01/1999	3	Tank 43 Hydrogen Monitor out of calibration	SR-WSRC-HTANK-1999-0018	EM	Unusual	Update/Final	05/24/1999	05/26/1999
05/01/1999	3	Improper Shipment of Hazardous Material; 14 DOT Violations Occurred.	SR-WSRC-LTA-1999-0018	EM	Off-Normal	Update Final	05/12/1999	06/22/1999

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
05/01/1999	3	Oxygen Analyzer Indicates Oxygen Content Greater than 5 percent for Glove box in Utilities Control Room.	RFO-KHLL-PUFAB-1999-0028	EM	Off-Normal	Update/Final	05/11/1999	06/09/1999
05/01/1999	3	Small Bottle with Unknown Content is Discovered During Sampling; one third ounce of liquid and crystal mixture of undetermined content. Item suspected of being shock sensitive.	ORO-BJC-PGDPENVRES-1999-0005	EM	Off-Normal	Update/Final	05/28/1999	07/12/1999
05/01/1999	3	Exceedance of Respiratory Protection Factor for Lead; abrasive blasting of lead-based paint causes contractor personnel to exceed respiratory protection factor .	ORO-BJC-K25GENLAN-1999-0009	EM	Off-Normal	final	05/06/1999	06/25/1999
05/01/1999	3	Annulus Conductivity Probe Taken Out of Service ; Failure to recognize entry into a LCO .	SR-WSRC-HTANK-1999-0014	EM	Off-Normal	Final	05/11/1999	05/24/1999
05/01/1999	3	Degradation of Tank Hydrogen Monitor - Rollup Report; Similar Event SR-WSRC-HTANK-1999-017, ON 4/30/99 ; Both events "rolled up" into this report.	SR-WSRC-HTANK-1999-0013	EM	Off-Normal	Final	04/29/1999	05/24/1999
05/01/1999	3	Decontamination Shower Drains Found Not to be Isolated from the Waste Drain Lines, Providing Greater Leak Area Beyond Basis fo Interim Operation.	ALO-AO-MHSM-PANTEX-1999-0039	DP	Unusual	Final	05/03/1999	07/12/1999

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
05/01/1999	3	Inadvertent Fire Suppression Dry Chemical Discharge; no potential for oxygen deficient atmosphere.	ALO-KO-SNL-NMFAC-1999-0005	DP	Off-Normal	Final	04/14/1999	05/24/1999
05/01/1999	3	Mischaracterization of Waste Oil for Recycling; waste oil had levels of PCBs in excess of acceptance criteria resulting in 27K fine.	OAK-LBL-EHS-1999-0003	EM	Off-Normal	final	05/06/1999	06/22/1999
05/01/1999	3	50 ml of a Hexane and Acetone Mixture Was Spilled onto the Floor ; no injuries reported.	RL-PHMC-ANALLAB-1999-0012	EM	Off-Normal	Final	05/11/1999	07/26/1999
Total for Class		19						
05/01/1999	4	Hydraulic Oil Leak; 70 gallons of oil leaks from Lift System into surrounding soil.	NVOO-BNLV-NTS-1999-0012	DP	Off-Normal	Notification	02/11/1999	05/13/1999
05/01/1999	4	Diesel Fuel Spill totalling 85 gallons at 100-H Area	RL-BHI-REMACT-1999-0004	EM	Off-Normal	Final	05/14/1999	06/08/1999
05/01/1999	4	A subsurface potable water line fails releasing potable water and sediment into the Los Alamos Canyon Stream Course.	ALO-LA-LANL-PHYSTECH-1999-0008	DP	Off-Normal	Update/Final	05/16/1999	06/28/1999
05/01/1999	4	Sewage release into storm drain caused by tree root obstruction.	OAK-SU-SLAC-1999-0002	SC	Off-Normal	Update	05/11/1999	06/30/1999
05/01/1999	4	Mercury Batteries in 90 Day Storage Area Exceeded 90 Day sStorage Limit.	RFO-KHLL-774OPS-1999-0002	EM	Off-Normal	Update/final	05/04/1999	06/18/1999

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
05/01/1999	4	Noncompliance with Department of Transportation (DOT) Hazardous Materials Regulations when Containers Labeled as Empty turn out to contain a Quantity of RCRA Waste Material.	ORO-BJC-K25-WASTMAN-1999-0008	EM	Off-Normal	Update/Final	05/18/1999	07/02/1999
05/01/1999	4	Bacterial Contamination Found in INTEC Potable Water System; no hazards to humans.	ID-LITC-LANLORD-1999-0006	EM	Off-Normal	Final	05/05/1999	06/23/1999
05/01/1999	4	An Unreviewed Safety Question (USQ) exists due to a Sodium Leak Accident Analysis Exceeding the Limit in the Final Safety Analysis Report.	RL-PHMC-FFTF-1999-0006	NE	Unusual	Update/final	05/07/1999	06/30/1999
05/01/1999	4	Improper Packaging of FedEx Package Results in Unintentional Release of Hazardous Material	CH-AA-ANLW-ANLW-1999-0003	NE	Off-Normal	Update/Final	05/06/1999	06/09/1999
05/01/1999	4	Failure of an Argon Check Valve causes 500 lbs of Hydrogen to Back-Flow through valve into Argon Supply Line.	CH-AA-ANLW-FASB-1999-0001	NE	Off-Normal	Update/Final	05/04/1999	06/09/1999
05/01/1999	4	Potential RCRA Permit Violation While Performing Annual Preventive Maintenance.	ID-LITC-RWNS-1999-0005	EM	Off-Normal	Final	05/11/1999	06/30/1999
05/01/1999	4	Diesel Fuel and Oil Release Requiring Approx. 35 to 40 Cubic Yards of Soil Removal; event notified on 5/5/99	HQ-SAYM-YMSGD-1999-0005	RW	Off-Normal	Update/Final	02/10/1999	05/24/1999

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
Total for Class			12					

—